




1 PANEL ON WOOD FURRING




2 PANEL ON STUD




3 THROUGH POST




4 SILL / GLAZING




5 HEAD CONDITION FULL OR RAIL HEIGHT




6 CEILING HEAD CONDITION




7 FULL HEIGHT DOOR FRAME WITH STANDARD SNAP HEADER




8 GLAZED HEAD AT CEILING




9 FLOOR CONDITION




10 FLOOR CONDITION STUD WITH STUD CLIP




11 FLOOR CONDITION INTEGRAL CLIP ON BASE




12 FLOOR CONDITION CLIP ON BASE W/ CLIP




13 PARTITION JOINT/NEF ALUMINUM "H" STUD




14 PARTITION JOINT/NEF ALUMINUM "H" STUD WITH NON-PROGRESSIVE EDGE CLIP STAGGERED JOINT




15 DOOR JAMB AND HEADER SOLID PARTITION




16 OUTSIDE CORNER




17 TERMINATION




18 FINISHED END / UH-375




19 FINISHED END / TT-375




20 GLAZED MULLION




21 FULL GLAZING - NO BASE



22 DOOR FRAME WITH GLASS TRANSITION



23 TRANSITION GLASS TO PANEL



24 TRANSITION TO GLASS PANEL

